



**A.G. SPANOS PROPELLER SERVICE
STOCKTON, CALIFORNIA**

Propeller Logbook

PROPELLER MAINTENANCE RECORD

^{single}
LEFT ENGINE

Hub Model HC-A2VK-1

Blade Design V8433-7

Diameter 77"

Hub Ser. No. 5396

Blade Ser. Nos. _____

No. 1 A23311

No. 2 A23321

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High 32.2° @ 30" sta. Low 14.6° @ 30"

Feather _____ Reverse _____

Governor Model _____

~~RIGHT ENGINE~~

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No. _____

Blade Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

[illegible]

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
7/18/84		Propeller disassembled	
Tach 4634.0		and inspected as per	
		AD #85-14-10	
		Carl Nelson A5 P 1924123	
7/24/92	4737.3	I certify this prop has been inspected in accord-	
S.M.O.H.		ance with an annual inspection and was determined to be in	
103.3 HRS		an airworthy condition D.R. Bord D. Bord 1232669 I.A.	
Sept. 24, 1992	Tach 4788.7	I certify this propeller has been inspected in	
		accordance with an annual inspection and was determined to be	
		in an airworthy condition D.R. Bord D. Bord 1232669 I.A.	

