

Date: 12/29/2023	Make/Model: Piper PA-24-260	Tail #: N9394P	Serial #: 24-4897
Airframe Hours:			
Misc: 4896.5			
Engine: Lycoming IO-540-N1A5	Serial #: L-7938-48	Hours: 616.82	
Propeller: Hartzell HC-E2Y Series	Serial #: DK1436E	Hours: 281.0	

Piper PA-24-260

AD# Category	Eff Date 08/31/61	Subject Fuel Selector Valve Handles	Date/Hours at Compliance	Method of Compliance N/A not installed	Rec	Date/Hours Next Due	Signature and Number Andrew Morgan AP3184876IA
61-16-06 Airframe	08/31/61	Fuel Selector Valve Handles		N/A not installed			Andrew Morgan AP3184876IA
62-26-05 Airframe	12/05/62	Exhaust System		N/A by SN			Andrew Morgan AP3184876IA
63-27-03 Airframe	01/23/64	Landing Gear Retraction Motor		N/A by SN			Andrew Morgan AP3184876IA
65-11-04 Airframe	05/11/65	Stabilator Control System		N/A not installed			Andrew Morgan AP3184876IA
66-18-04 Airframe	08/10/66	Baggage Door Latch		N/A by SN			Andrew Morgan AP3184876IA
68-05-01 Airframe	03/31/68	Exhaust Mufflers		N/A by Model	Yes*		Andrew Morgan AP3184876IA
71-12-05 Airframe	06/16/71	Electric Trim Switch	12/16/71 382.0	Complied with previously			Andrew Morgan AP3184876IA
72-22-05 Airframe	12/26/74	Operation Limitation Placard	7/20/73 602.0	Complied with previously			Andrew Morgan AP3184876IA
74-13-03 Airframe	04/30/76	Stabilator Attach Bolts	2/1/75 794.0	Complied with stainless bolts installed no further action required	Yes*		Andrew Morgan AP3184876IA
75-05-02 Airframe	02/21/75	Engine Oil		N/A not installed	Yes*		Andrew Morgan AP3184876IA
75-12-06 Airframe	06/05/75	Fin Forward Spar	1/2/2024 4896.5	Inspected FWD spar channel per Para (b) of AD, no defects noted	Yes	4996.5	Andrew Morgan AP3184876IA
75-27-08 Airframe	06/03/76	Stabilator Bearing Support Fittings	11/21/79 2052.3	Complied with previously			Andrew Morgan AP3184876IA
76-19-07 Airframe	09/29/76	Stabilator Balance Weight Tube		N/A not installed per Piper SL 687			Andrew Morgan AP3184876IA
77-08-01 Airframe	04/18/77	Aileron Spar Cracks	1/30/80 2075.6	Complied with previously by installation of Kit 760-914 no further action required	Yes*		Andrew Morgan AP3184876IA

77-09-10 Airframe	05/12/77	Electric Trim Switch		Complied with by Piper SB 587			Andrew Morgan AP3184876IA
77-13-21 Airframe	12/16/77	Landing Gear Collapse	11/12/2022 4870.6	Bungees replaced due again at 5370.6 or by 11-12-2025, visual inspection to verify airworthy condition	Yes	11/12/2025 5370.6	Andrew Morgan AP3184876IA
79-20-10 Airframe	10/04/79	Incorporation of Piper Kit 763893	1/30/80 2075.6	Complied with previously by installation of kit 763-893 no further action required	Yes*		Andrew Morgan AP3184876IA
82-23-01 R1 Airframe	04/07/83	Flap Extension Limitation Placard		N/A not installed			Andrew Morgan AP3184876IA
83-19-03 Airframe	09/30/83	Spar Cap Inspection		Complied with per Piper SB 751			Andrew Morgan AP3184876IA
85-02-05 R1 Airframe	11/21/97	Placard Installation		Complied with placard installed			Andrew Morgan AP3184876IA
91-21-09 Airframe	11/29/91	Air Induction System		N/A by SN			Andrew Morgan AP3184876IA
94-13-10 Airframe	08/12/94	Stabilizer Torque Tube Bearing Support	1/2/2024 4896.5	Visual/Manual inspection complied with per SB411A no defects found	Yes*	4996.5	Andrew Morgan AP3184876IA
97-01-01 R1 Airframe	12/08/98	Main Gear Sidebrace Stud	3/19/01 4085.34	Complied with	Yes*	5085.34	Andrew Morgan AP3184876IA
99-05-09 Airframe	03/19/99	Induction Air Filter		N/A not installed			Andrew Morgan AP3184876IA
12-17-06 Airframe	10/22/12	Stabilator Horn Assembly	10/1/21 4855.6	Inspection done SB 1189, dated 4/29/10	Yes	10/1/26 5355.6	Andrew Morgan AP3184876IA
15-24-05 Airframe	01/12/16	Fuel System Management Placard	6/11/17 4715.0	Placard installed and placed in POH previously complied with			Andrew Morgan AP3184876IA
23-09-09 Airframe	07/17/23	Exhaust Tailpipe V-Band Coupling		N/A non-turbo charged engine installed	Yes		Andrew Morgan AP3184876IA

Engine: Lycoming IO-540-N1A5

AD# Category	Eff Date	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
63-14-03 Engine	07/06/63	Oil Pump Drive Shaft		N/A by SN	Yes*		Andrew Morgan AP3184876IA
66-20-04 Engine	08/27/66	Oil Filter Adapter Gasket		N/A not installed			Andrew Morgan AP3184876IA
75-08-09 Engine	08/18/77	Oil Pump Drive Shaft and Impeller		N/A by SN			Andrew Morgan AP3184876IA
75-09-15 Engine	04/30/75	Bendix Fuel Injector Flow Divider Cover Gasket		N/A by PN			Andrew Morgan AP3184876IA

12-03-06 Engine	02/24/12 AVStar Fuel Servo Diaphragm		N/A not installed			Andrew Morgan AP3184876IA
12-19-01 Engine	10/24/12 Crankshaft Replacement		N/A crankshaft was not replaced in timeframe N/A engine model not listed in MSB			Andrew Morgan AP3184876IA
15-19-07 Engine	11/03/15 Fuel Injector Fuel Lines and Clamps	1/2/2024 4896.5	Visual inspection of injector lines and clamps no defected noted	Yes	4996.5	Andrew Morgan AP3184876IA
17-16-11 Engine	08/15/17 Connecting Rod Failure	7/11/18 4750.3	N/A by overhaul date			Andrew Morgan AP3184876IA

Propeller: Hartzell HC-E2Y Series

AD# Category	Eff Date	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
64-20-01 Propeller	08/28/64	Pitch Change Blocks		N/A by model	Yes*		Andrew Morgan AP3184876IA
71-21-09 Propeller	06/27/72	Spring Backup Kit		N/A by model			Andrew Morgan AP3184876IA
01-07-03 Propeller	06/04/01	BASCO Serviced Propellers		N/A by SN			Andrew Morgan AP3184876IA
01-23-08 Propeller	12/24/01	Hub Fillet Radius Crack Inspection		N/A by application	Yes*		Andrew Morgan AP3184876IA
03-01-03 Propeller	01/23/03	Propeller Assembly Removal		N/A by SN			Andrew Morgan AP3184876IA
03-13-17 Propeller	07/18/03	T and W Serviced Propellers		N/A no record of service by listed company			Andrew Morgan AP3184876IA
05-14-11 Propeller	08/17/05	Southern California Propeller Serviced Propellers		N/A no record of service by listed company			Andrew Morgan AP3184876IA
06-24-07 Propeller	01/03/07	Oxford Aviation/CSE Aviation Serviced Propellers		N/A no record of service by listed company			Andrew Morgan AP3184876IA
07-26-09 Propeller	01/30/08	Fatigue Cracks	10/10/13 4616.5	Complied with at overhaul			Andrew Morgan AP3184876IA
09-22-03 Propeller	11/12/09	Propeller Hub Crack Inspection		N/A by engine model	Yes*		Andrew Morgan AP3184876IA

Appliance: Power Plant - Ignition - Switches

AD# Category	Eff Date	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
76-07-12 Appliance	08/30/77	10-357XXX, 10-126XXX, 10-157XXX - Switch Repair or Replacement	1/2/2024 4896.5	Checked operation of switch to off position per AD, no defects noted	Yes	4996.5	Andrew Morgan AP3184876IA

78-23-10 11/07/78 Engine	Bendix RSA Series Fuel Injector Bellows Seal		N/A by PN			Andrew Morgan AP3184876IA
79-04-05 09/26/79 Engine	Bendix RSA Series Fuel Injectors Diaphragm		N/A by PN			Andrew Morgan AP3184876IA
92-12-05 07/10/92 Engine	Piston Pin Failure		N/A by PN			Andrew Morgan AP3184876IA
93-11-11 06/21/93 Engine	Diaphragm Fuel Pumps Overhauled (by AAI) - Remove Affected Pump and Replace		N/A not installed			Andrew Morgan AP3184876IA
95-07-01 04/12/95 Engine	Superior Air Parts Connecting Rod Bolts		N/A by PN			Andrew Morgan AP3184876IA
96-09-10 07/15/96 Engine	Oil Pump Impeller Failure	12/13/04 4552.98	Complied with previously			Andrew Morgan AP3184876IA
96-23-03 12/17/96 Engine	High Pressure Fuel Pumps		N/A by date code			Andrew Morgan AP3184876IA
97-15-11 08/12/97 Engine	Piston Pin Failure		N/A by PN			Andrew Morgan AP3184876IA
98-17-11 10/19/98 Engine	Crankshafts Installed by Nelson Balancing Service		N/A no repairs by Nelson			Andrew Morgan AP3184876IA
02-19-03 09/20/02 Engine	Crankshaft Failure		N/A by SN			Andrew Morgan AP3184876IA
03-14-03 08/14/03 Engine	Rotary Fuel Pump Leaks		N/A not installed	Yes*		Andrew Morgan AP3184876IA
04-05-24 03/30/04 Engine	Crankshaft Gear Retaining Bolts		N/A by PN			Andrew Morgan AP3184876IA
04-10-14 06/25/04 Engine	Crankshaft Gear Retaining Bolt	10/15/13 4616.5	Complied with due again at prop strike or crank removal	Yes	Prop Strike or crank removal	Andrew Morgan AP3184876IA
06-10-21 06/22/06 Engine	ECi Connecting Rods	10/15/13 4616.5	N/A not installed			Andrew Morgan AP3184876IA
06-12-07 07/11/06 Engine	ECi Cylinder Assemblies		N/A not installed			Andrew Morgan AP3184876IA
07-04-19 R1 05/07/07 Engine	Superior Air Parts Cylinder Assemblies		N/A not installed			Andrew Morgan AP3184876IA
09-02-03 02/09/09 Engine	RSA-5 or RSA-10 Series - Fuel Injection Servo Plug Gasket	10/15/13 4616.5	Complied with previously	Yes*		Andrew Morgan AP3184876IA
09-26-12 02/04/10 Engine	ECi Cracked Cylinder Assemblies		N/A not installed	Yes		Andrew Morgan AP3184876IA