

*Propeller LOG #2*

**THE adlog<sup>TM</sup> AIRCRAFT MAINTENANCE RECORDKEEPING SYSTEM**

**PROPELLER  
MAINTENANCE  
RECORDS**

# PROPELLER MAINTENANCE RECORDS

Log No. 2

Aircraft Registration No. N 4260 \$

Propeller Manufacturer HANTZELL

Hub Model PHC-C34F-1RF

Blade Design No. F 8068

Hub Serial No. EE 4203 B

Blade Serial No's.

1. J 75175

2. J 75180

3. J 75178

4. \_\_\_\_\_

Pitch Range:

High 36.4 - 36.5 1/2 Low 12.3 1/2 - 12.4

Feather N/A Reverse N/A

Governor Manufacturer WOODWARD

Model No. D210680

Serial No. 1194664

Date installed on aircraft 8/6/2002

Time Between Overhauls (TBO) 2000 Hours

If used on multi-engine aircraft:

- Right       Left  
 Front       Rear

STC SA01548CH

(All applicable information must be filled in)



**AEROTECH PUBLICATIONS INC.**

www.adlog.com  
PO BOX 1359 / SOUTHOLD, NY 11971-0965  
(631) 765-9375  
1-800-235-6444  
FAX: (631) 765-9359





**Executive Flight Services**  
 151 Texas Way  
 Fort Worth, TX 76106  
 Phone: (817) 740-9904 Fax: (817) 740-9906



Make / Model: Beech Bonanza A36 Serial No. E-959  
 Propeller: Hartzell PHC-C34F-1RF S/N EE 4203 B  
 Hobbs: 5290.7  
 Tach: 5613.9

Reg. No. N4260S

**Propeller Log Entry**

Date: 09/28/2010

Completed the following inspections:  
 Accomplished Annual Inspection IAW Hawker Beechcraft Bonanza Inspection Guide.

I certify this Propeller has been inspected IAW Hawker Beechcraft 100Hr/Annual inspection, in accordance with the current Federal Aviation Regulations, found to be in an Airworthy condition and is approved for return to service.

Signature Monty Chad Michael Certificate # A&P 2736982 IA



**Executive Flight Services, Incorporated**  
 151 Texas Way  
 Fort Worth, TX 76106



Model: PHC-C3YF-1RF Serial No: EE 4203 B Acft. Reg. No: N4260S  
 TSN: 5780.5 **Maintenance Log Entry** Date: 24-Oct-11

1. 100 hour/Annual inspection accomplished in accordance with Hawker Beechcraft Corporation Bonanza 36 Long Form Inspection Guide and 14CFR part 43 Appendix D.
2. 100 hour lubrication accomplished.

I certify this propeller has been and inspected in accordance with the current Federal Aviation Regulations and is approved for return to service for the above work accomplished.

Signature James A. Brooks Certificate # A&P 523476442



EXECUTIVE FLIGHT SERVICES  
 13160 Rhodus Rd.  
 Excelsior Spring MO 64024

Make: Hartzell Model: PHC-C3YF-1RF S/N: EE4203B Reg: N4260S Date: January <sup>14</sup> 2013

Prop TT: 882.7 Hobbs: 5590.6

1. Performed 100 hour inspection in accordance with Hawker Beechcraft Corporation Bonanza 36 Long Form Inspection Guide and 14CFR part 43 Appendix D. Post maintenance operational/leak check satisfactory at this time.

I certify this propeller has been repaired and/or inspected in accordance with the current Federal Aviation Regulations and is approved for return to service for the above work accomplished.

Signature Josh Johnson Josh Johnson A&P 3546051 W/O No. GPH 2438





FIRST CLASS  
POSTAGE  
PAID  
CHITA, KS  
PERMIT #135



Invoice #328769491

Dec 10, 2025 2:41:48 PM  
Waypoint Aviation Services

Express Item x1 \$678.52

Subtotal \$678.52  
Tax \$0.00  
Total \$678.52

Visa 1885 (Contactless EMV)  
Auth Code: 010882

Application Label: VISA CREDIT  
BRIC #: 07XMT1WVLSH1R6DFBAV  
Approved Online  
AID: A0000000031010  
AC: 908931D9AD010394  
Response Code: 00

Waypoint Aviation Services  
6873 Flight Rd  
Riverside, CA 92504  
(951) 977-8361  
<https://www.waypointmro.com>  
[fly@waypointMRO.com](mailto:fly@waypointMRO.com)

CUSTOMER COPY

Payments are due upon completion of the

Page No.

DATE

31 July 2019

N4260S

S/N E-959

ACTT: 6572.6

Hobbs: 595.1

Propeller: Hartzell PHC-C34F-1RF

S/N EE4203B

WORK

Performed annual/100 hour inspection IAW Beechcraft Annual Inspection guide 98-32227R.

Performed 100 Lube per Beech A36 Maintenance Manual.

I CERTIFY THAT THIS propeller  
HAS BEEN INSPECTED IN ACCORDANCE WITH A(N)  
annual/100 hr INSPECTION AND WAS DETERMINED  
TO BE IN AN AIRWORTHY CONDITION.

ACTT 6572.6 DATE 31 July 2019

FRANK E. CECILIA A&P 3439119 IA

31 July 2020

N4260S

S/N E-959

ACTT: 6631.4

Hobbs: 656.0

Propeller: Hartzell PHC-C34F-1RF

S/N EE4203B

Performed annual/100 hour inspection IAW Beechcraft Annual Inspection guide 98-32227R.

Performed 100 Lube per Beech A36 Maintenance Manual.

I CERTIFY THAT THIS PROP  
HAS BEEN INSPECTED IN ACCORDANCE WITH A(N)  
ANNUAL/100HR INSPECTION AND WAS DETERMINED  
TO BE IN AN AIRWORTHY CONDITION.

ACTT 6631.4 DATE 31 July 2020

FRANK E. CECILIA A&P 3439119 IA

SUB-TOTALS this page

TOTALS-Carry forward to next page

December 10, 2025



FIRST CLASS  
POSTAGE  
PAID  
CHITA, KS  
PERMIT #135

**WAYPOINT**  
AVIATION SERVICES

Invoice #328769491

Dec 10, 2025 2 41 48 PM  
Waypoint Aviation Services

Express Item x1 \$678.52

Subtotal \$678.52  
Tax \$0.00  
Total \$678.52

Visa 1885 (Contactless EMV)  
Auth Code: 010882

Application Label: VISA CREDIT  
BRIC #: 07XMT1WVLSH1R6DFBAV  
Approved Online  
AID: A0000000031010  
AC: 908931D9AD010394  
Response Code: 00


Waypoint Aviation Services  
6873 Flight Rd  
Riverside, CA 92504  
(951) 977-8361  
https://www.waypointmro.com  
fly@waypointMRO.com

CUSTOMER COPY

Payments are due upon completion of the


December 10, 2025

Page No. \_\_\_\_\_

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
				<p>Make: Hartzell S/N: EE4203B Prop: Removed propeller to change crank seal on engine and reinstalled and torqued with new o-ring P/N: C-3317-228.</p> <p>REG: N4260S Tach: 6725.0 Model: PHC-C3YF-1RF/F8068 Date: 5-19-2022</p> <p>The above-mentioned work has been accomplished with reference to Beechcraft Bonanza Maintenance Manual.</p> <p>Date: 11-5-2021 Name: <u>Daniel Diamond</u> Daniel Diamond AP 2852503</p>
				<p>Date: November 20, 2022 Tach Time: 6784.5 Hobbs: 821.8 TSMOH: 1783.4</p> <p><b>CAMARILLO AIRCRAFT SERVICE</b>  375 Durley Ave. Ste B Camarillo, CA 93010 (805) 388-1322</p> <p>Propeller Logbook Entry Aircraft Reg: N4260S S/N: E-959</p> <p>Completed Annual Inspection of this Hartzell Model PHC-C3YF-1RF Propeller (S/N EE4203B) in accordance with FAR Part 43, Appendix D. Dressed nicks on one blade. Checked hub, spinner, &amp; backplate for security and leaks. Checked ADs thru inspection date.</p> <p>I certify that this Propeller has been inspected in accordance with Annual Inspection and was determined to be in airworthy condition.</p> <p>Signature: <u>Richard Fleck</u> Richard Fleck, 3521570 IA</p>
				SUB-TOTALS this page
				TOTALS-Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page

wo: 5866 Propeller - page 1 of 1

**WAYPOINT AVIATION SERVICES** 


Waypoint Aviation Services · 6873 Flight Rd. · Riverside, CA 92504 · 951-977-8361

**N4260S** **Hartzell, PHC-C3YF, S/N: EE4203B** **February 29, 2024**  
 TSOH: 189.9 Tach: 6884.5


Filed and dressed propeller blades (and/or) painted propeller blade face.

I certify this Propeller has been inspected in accordance with an Annual Inspection and was found to be in an Airworthy Condition.

This propeller identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Details of work performed are on file with Waypoint Aviation Services under work order: 5866.

Matthew LaPrade A&P IA 3741762 

wo: 6048 Propeller - page 1 of 1

**WAYPOINT AVIATION SERVICES** 


Waypoint Aviation Services · 6873 Flight Rd. · Riverside, CA 92504 · 951-977-8361

**N4260S** Tach: 6962.0 **April 17, 2025**  
 SMOH: 267.4


Filed and dressed propeller blades (and/or) painted propeller blade face.

I certify this Propeller has been inspected in accordance with an Annual Inspection and was found to be in an Airworthy Condition.

This propeller identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Details of work performed are on file with Waypoint Aviation Services under work order: 6048.

Matthew LaPrade A&P IA 3741762 

wo: 6157 Propeller - page 1 of 1

**WAYPOINT AVIATION SERVICES** 


Waypoint Aviation Services · 6873 Flight Rd. · Riverside, CA 92504 · 951-977-8361

**N4260S** PTSN: 6831.6 **May 15, 2026**  
 hobbs: 1690.0

Filed and dressed propeller blades (and/or) painted propeller blade face.

I certify this Propeller has been inspected in accordance with an Annual Inspection and was found to be in an Airworthy Condition.

This propeller identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Details of work performed are on file with Waypoint Aviation Services under work order: 6157.

Matthew LaPrade A&P IA 3741762 

				<b>SUB-TOTALS</b> this page
				<b>TOTALS</b> -Carry forward to next page



QUALITY AND  
BY REGISTERED MARKS

117000

5 AUTHORITY AND BASIS FOR ISSUE  
This airworthiness certificate  
date of issuance, the aircraft  
therefor, to be in condition  
comprehensive and detailed  
Aviation, except as noted by  
Exceptions:

6 TERMS AND CONDITIONS  
Unless sooner surrendered,  
this airworthiness certificate  
performed in accordance with  
aircraft is registered in the

DATE OF ISSUANCE  
NOV. 29, 1976

Any alteration, reproduction, or  
revision not exceeding 3 years  
IN ACCORDANCE WITH APPLICABLE FEDERAL

117000 2 17 67

DEPARTMENT OF  
COMMERCE

NATIONALITY AND  
REGISTRATION MARK

MANUFACTURER AND  
BEECH

ICAO Aircraft Address

ISSUED TO  
LUQA AVIA  
1517 PERIN  
WEST PALM

It is certified that the  
Aviation Administration  
International Civil Aviation  
and regulations issued

DATE OF ISSUE  
EXPIRATION DATE

92503 (102018)



STAPLES