



DATE


31 July 2019  
N4260S  
S/N E-959  
ACTT: 6572.6  
Hobbs: 595.1  
Propeller: Hartzell PHC-C34F-1RF  
S/N EE4203B

WORK

Performed annual/100 hour inspection IAW Beechcraft Annual Inspection guide 98-32227R.  
Performed 100 Lube per Beech A36 Maintenance Manual.

I CERTIFY THAT THIS propeller  
HAS BEEN INSPECTED IN ACCORDANCE WITH A(N)  
annual/100 hr INSPECTION AND WAS DETERMINED  
TO BE IN AN AIRWORTHY CONDITION.

ACTT 6572.6 DATE 31 July 2019


  
FRANK E. CECILIA A&P 3439119 IA

31 July 2020  
N4260S  
S/N E-959  
ACTT: 6631.4  
Hobbs: 656.0  
Propeller: Hartzell PHC-C34F-1RF  
S/N EE4203B

Performed annual/100 hour inspection IAW Beechcraft Annual Inspection guide 98-32227R.  
Performed 100 Lube per Beech A36 Maintenance Manual.

I CERTIFY THAT THIS PROP  
HAS BEEN INSPECTED IN ACCORDANCE WITH A(N)  
ANNUAL/100HR INSPECTION AND WAS DETERMINED  
TO BE IN AN AIRWORTHY CONDITION.

ACTT 6631.4 DATE 31 July 2020

  
FRANK E. CECILIA A&P 3439119 IA

SUB-TOTALS this page

TOTALS-Carry forward to next page

28 October 2021

N4260S

S/N E-959

ACTT: 6676.9

Hobbs: 705.8

Propeller: Hartzell PHC-C34F-1RF

S/N EE4203B


FORMING WORK

DATE

Performed annual/100 hour inspection IAW Beechcraft Annual Inspection guide 98-32227R.

I CERTIFY THAT THIS Prop  
HAS BEEN INSPECTED IN ACCORDANCE WITH A(N)  
Annual/100 HR INSPECTION AND WAS DETERMINED  
TO BE IN AN AIRWORTHY CONDITION.

ACTT 6676.9 DATE 28 OCT 2021

  
FRANK E. CECILIA A&P 3439119 IA

Palm Beach Aircraft Propeller, Inc.  
2633 Lantana Rd, Ste. 23 Building 1501  
Lantana, Florida 33462  
FAA Certified Repair Station No. LU4R349M


Date: 1/21/2022

Prop Mod: PHC-C3YF-1RF/F8068 Ser # EE4203B

Propeller Total Time: 1665.6 T.S.O. 0

This propeller was Overhaul

SERVICE WITH NYCO GREASE PER HC-SL-61-366  
It was functionally tested in accordance with current Federal Aviation  
Regulations and was found air worthy for return to service. Pertinent  
details of the repair are on file at this agency under work order 21915

Michael F. O'Neill   
Authorized Signature

Form # PR 28 LB

Rev. 0. 2-1-2018

1 February, 2022

N4260S


S/N E-0959

ACTT 6694.6

HOBBS 724.6

Removed and reinstalled prop. Overhauled p/n PHC-C3YF-1RF/F8068 s/n EE4203B installed. Ops and leak check good. Prop TSN: 1665.6 TSO: -0-

I certify that the above maintenance was performed in an airworthy manner IAW Beechcraft Bonanza 36 shop manual and is approved for return to service.

  
Frank E Cecilia A&P 3439119 IA

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page

Make: Hartzell  
S/N: EE4203B  
Prop:


REG: N4260S  
Tach: 6725.0

Model: PHC-C3YF-1RF/F8068  
Date: 5-19-2022


Removed propeller to change crank seal on engine and reinstalled and torqued with new o-ring P/N: C-3317-228.

The above-mentioned work has been accomplished with reference to Beechcraft Bonanza Maintenance Manual.

Date: 11-5-2021

Name   
Daniel Diamond AP 2852503


Date: November 20, 2022  
Tach Time: 6784.5  
Hobbs: 821.8  
TSMOH: 1783.4



Propeller Logbook Entry  
Aircraft Reg: N4260S  
S/N: E-959

Completed Annual Inspection of this Hartzell Model PHC-C3YF-1RF Propeller (S/N EE4203B) in accordance with FAR Part 43, Appendix D. Dressed nicks on one blade. Checked hub, spinner, & backplate for security and leaks. Checked ADs thru inspection date.

I certify that this Propeller has been inspected in accordance with Annual Inspection and was determined to be in airworthy condition.


Signature  Richard Fleck, 3521570 IA

**SUB-TOTALS** this page

**TOTALS**-Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page

wo: 5866 Propeller - page 1 of 1

  
**WAYPOINT AVIATION SERVICES**

Waypoint Aviation Services · 6873 Flight Rd. · Riverside, CA 92504 · 951-977-8361


---

**N4260S** **Hartzell, PHC-C3YF, S/N: EE4203B** **February 29, 2024**  
 TSOH: 189.9 Tach: 6884.5


Filed and dressed propeller blades (and/or) painted propeller blade face.

I certify this Propeller has been inspected in accordance with an Annual Inspection and was found to be in an Airworthy Condition.

This propeller identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Details of work performed are on file with Waypoint Aviation Services under work order: 5866.

Matthew LaPrade A&P IA 3741762 

wo: 6048 Propeller - page 1 of 1

  
**WAYPOINT AVIATION SERVICES**

Waypoint Aviation Services · 6873 Flight Rd. · Riverside, CA 92504 · 951-977-8361

---

**N4260S** Tach: 6962.0 **April 17, 2025**  
 SMOH: 267.4

Filed and dressed propeller blades (and/or) painted propeller blade face.

I certify this Propeller has been inspected in accordance with an Annual Inspection and was found to be in an Airworthy Condition.

This propeller identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Details of work performed are on file with Waypoint Aviation Services under work order: 6048.

Matthew LaPrade A&P IA 3741762 