



The Standard

AIRCRAFT LOG

ASA-SL-2

Manufacturer VARGA Model 2150A
Serial VAC 86-77 Registration Number N4630V
Date of Manufacture 09-26-77

Engine(s) currently installed:

Manufacturer LYCOMING Model 0320-A2C Serial L47343-27A
Manufacturer _____ Model _____ Serial _____

Propeller(s) currently installed:

Manufacturer SENSENICH Model 74DM6-0-61
HUB Model 74DM6-0-61 Serial A44871 Serial _____
Blade Model _____ Serial _____ Serial _____
Blade Model _____ Serial _____ Serial _____

Registered Owner Record

Name Air TRANSPORT LLC Address 2119 WINSTON AVE

City Louisville State KY From _____ To _____

~~Name~~ C/O Paul ROBERTSON Address _____

City 40205-2535 State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____


City _____ State _____ From _____ To _____

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations		
	Registration	Work Order	Date	TTAF	TACH	HOBBS
	N4630V	RS4241	03/05/20		3113.7	2260.7

Verified pressure altitude correlation to primary altimeter and found to comply with 14 CFR 43 App. E. Performed ATCRBS transponder tests required by 14 CFR Part 91.413 and found to comply with 14 CFR Part 43 Appendix F. ADS-B out system was found to be in compliance with 14 CFR Part 91.227 (ref. AFS-360-2017-1)


Transponder: Appareo STRATUS ESG S/N 079590

Elizabethtown Flying Service, Inc.
Addington Field, EKX


Jeff Lawson, 2824535
Repair Station AO5R733M

Airframe Cessna Reg: N4630V S/N: VAC86-77 Tach Time: 3125.71 Date 12/6/2022
Engine Lycoming Model: O-320-A2C S/N: L-49848-27A
Propeller Sensenich Model: 74DM6-0-61 S/N: A44871

Comply with an Annual Inspection. Removed inspection panels Removed Gascolator inspect and reinstalled. Complied with FAR91.207D inspection on Replaced ELT Battery: p/n BP-1030.C/W AD 76-07-12 Bendix Switch operation check no defects noted. AD research AD'S to this date. Lubricated aircraft. Reinstall inspection panels. I certify that this aircraft has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.


Steven Sheeley A&P 30998971A

YEAR 20 <u>23</u> DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
6/30	3170.7			INSTALLED TRAMS-CAL MODEL SSD120-35C-RS2 ALTITUDE ENCODER. REPAIR ENCODER W/ARREST I/A/W T.C.I. SSD120-35C-RS232 OWNER/ INSTALLATION MANUAL, P/N 881625 REV. A. EXISTING MARCO ARREST ALTITUDE ENCODER LEFT AS MOUNTING SHELF. <i>Lawrence F. Johnson A&P/IA 3486165</i>

1/7/2024 N4630V TT and TACH 3185.60 Aircraft opened for inspection. Inspected aircraft per scope and detail of CFR 43 appendix D. ELT operation check good per FAR 91-207d. ELT battery replace date January 2025 Inspected gascolator and found clean. Inspected wheel bearings. Replaced air filter replaced with new bracket P/N BA-4108

- AD 76-07-12 rev date 8/31/77 By operation of ignition switch, due again TACH 4543.23.
- See AD list for rest of AD compliance

Aircraft closed up and operation check good. I certify that this aircraft has been inspected IAW an annual and 100 hour inspection and has been found to be in airworthy condition. Lawrence F. Johnson A&P/IA 3486165 *Lawrence F. Johnson*

--	--	--

The Avionics Specialists, Inc.
 1410 Flightline Dr
 Lincoln, CA 95648
 +1 9166451441
 dlibertone@yahoo.com

Pass

Invoice

BILL TO
 norm fluhrer
 po box
 747
 mendicino, ca 95460

SHIP TO
 norm fluhrer
 po box
 747
 mendicino, ca 95460

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
83953	04/09/2024	\$200.00	04/09/2024	COD	

WORK ORDER #	AIRCRAFT TYPE	AIRCRAFT NUMBER
83953	varga	n4630v

ACTIVITY	QTY	RATE	AMOUNT
LABOR:DANA PERFORM VFR TEST AND CERTIFICATION	1	200.00	200.00
VFR Certification This aircraft transponder has been tested and inspected as required by FAR Part 91.413 and found to comply with FAR Part 43 Appendix F. The Avionics Specialists, Inc. FAA Approved Repair Station No. S3DR062N Signed <u>DANA LIBERTONE</u>	1	0.00	0.00
Date: <u>4-9-24</u>			
FLIGHT LOG ***** VARGA N4630V WRO 83953 This aircraft transponder has been tested and inspected as required by FAR Part 91.413 and found to comply with FAR Part 43 Appendix F. Signed: DANA LIBERTONE	1	0.00	0.00
Date <u>4-9-24</u> The Avionics Specialists, Inc. FAA-Approved Repair Station No.S3DR062N *****			

FLIGHT LOG

 VARGA N4630V WRO 83953
 This aircraft transponder has been tested and inspected as required by FAR Part 91.413 and found to comply with FAR Part 43 Appendix F.
 Signed: DANA LIBERTONE
 Date 4-9-24
 The Avionics Specialists, Inc.
 FAA-Approved Repair Station No.S3DR062N

THE AIRCRAFT AND/OR COMPONENTS IDENTIFIED ON THIS DOCUMENT WERE REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WERE FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY SIGNED _____ P.I. _____

SUBTOTAL	200.00
TAX	0.00
TOTAL	200.00
BALANCE DUE	\$200.00

3 MONTH WARRANTY ON ALL REPAIRS AND EXCHANGES. ALL WARRANTY WORK MUST BE COMPLETED BY OUR SHOP AT OUR FACILITY.