

LYCOMING

A Textron Company

ENGINE LOG

SSP-1872-1

LYCOMING
A Textron Company

652 Oliver Street
Williamsport, PA 17701 U.S.A.
570/323-6181

ENGINE LOG AND MAINTENANCE RECORD

RECORD OF LYCOMING VTO-320-D1A L-6035-55L
MAKE MODEL SERIAL

FROM AUGUST 20 11 TO _____ 20 _____
DETAILING TIME FROM 0.0 TO _____
HOURS HOURS

SSP-1872-1

© 1994 by Textron Lycoming "All Rights Reserved"

October 1994

ENGINE DESCRIPTION

Mfgr.	LYCOMING	Place	Williamsport, PA 17701	Date	
Type		Model		Serial No.	
Rated H.P.		Max. H.P.		Weight (Dry)	
Rated R.P.M.		Max. R.P.M.		Oil Pressure	
Bore		Stroke		Displacement	Cu. In.
Compression Ratio		Supercharger Ratio			
Reduction Gear Ratio					
Propeller	CATTO	Hub Design		Hub Serial No.	
Blade Design	3	Blade Serial No.	04081005	Blade Serial No.	
Max. Hub H.P.		Max. Blade H.P.			
Pitch	70	Diameter	68	Length	
Name					
Address					

ENGINE LOG

Serial No. L-6035-SSL

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
9/16	5	12	OIL CHANGE	Raymond P. Polesky	3592460
11/11/11	34	6	OIL CHANGE	Raymond P. Polesky	
2/12/12	43	8	OIL CHANGE	Raymond P. Polesky	
6/2/12	62	2	OIL CHANGE	Raymond P. Polesky	
6/5/12	62	3	REPLACED BATTERY - CONCORD R6-25XC	Raymond P. Polesky	
6/7/12	62	3	REPLACED PLANE POWER BOA ALTERNATOR		
10/20/12	109	39	CLEANED AIR FILTER, FUEL INLET SCREEN, CLEANED GAPPED & ROTATED PLUGS, ADJUSTED MAG, TIMING, CHECKED FITTINGS & CONNECTIONS OIL CHANGE AS PART OF ANNUAL CONDITIONAL INSPECTION	Raymond P. Polesky	3592460
			Page Total	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	
			Brought Forward		
			Total to Date		

ENGINE LOG

Serial No. _____

[illegible]

Serial No.

[illegible]

ENGINE LOG

Serial No. _____

[illegible]

Serial No.

[illegible]

ENGINE LOG

Serial No.

[illegible]

Serial No.

[illegible]

Serial No.



[illegible]

Serial No.

[illegible]

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
3/23/21	354	36	OIL & FILTER CHANGE, CHECKED FILTER FOR LEAK, PLACED BACK INTO SERVICE		35924060
10/23/2021			TACH 371.0 HOBBS 470.2 Annual conditional inspection completed, oil change, replaced air filter, Cleaned fuel filter inlet screen, gap and check spark plugs – rotated per spec. Mag timing check and cylinder pressure check was normal, all control linkages were found in good condition. Replaced fuel pressure hose (VA-102).		
			Raymond Peabody 35924060		
			Page Total	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	
			Brought Forward		
			Total to Date		

ENGINE LOG

Serial No.

[illegible]

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
			10/28/2023		
			TACH <u>412.1</u> HOBBS <u>529.3</u>		
			Annual conditional inspection completed, oil change, replaced air filter, gap		
			and check spark plugs – rotated per spec Mag timing check and cylinder		
			pressure check was normal, all control linkages were found in good condition.		
			Raymond Peabody 35924060		
			Page Total	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	
			Brought Forward		
			Total to Date		

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
			10/28/2024 TACH <u>435.1</u> HOBBS <u>562.5</u>		
			Annual conditional inspection completed, oil change, replaced air filter,		
			gap and check spark plugs – rotated per spec. Mag timing check and cylinder		
			pressure check was normal, all control linkages were found in good condition.		
			Raymond Peabody 35924060 <i>Raymond Peabody</i>		
			FAA AD-2023-00783-E AMENDMENT 39-22869		
			AD-2024-21-02 PUBLISHED 10/31/2024		
			DOES NOT APPLY TO THIS ENGINE- SHIP DATE 6/5/2008		
			Page Total	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	
			Brought Forward		
			Total to Date		

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
6/25/25			TACH 445.8 HORBS 577.2		
			REPLACED DYNON OIL TEMP SENSOR		
			TESTED & PLACED BACK IN SERVICE		
			Raymond Peobely 35924060		
			Page Total	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	
			Brought Forward		
			Total to Date		

