



The Standard

PROPELLER LOG

ASA-SEC

Propeller Record General Information

Propeller Manufacturer CATTO

Model 3 BLADE

Type 68X70

Hub Series # _____

Blade # _____

Date of Manufacture _____

Aircraft Installed On: PEABODY RAYMOND B
RV-9A

Serial #

90821

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: <u>2017</u>	Total Time in Service	Description
Date: <u>10/29/17</u>	277.6	
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # <u>35924060 Raymond Perleby</u>
Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____
Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

