

N9329L



SANTA MONICA PROPELLER

Propeller Logbook

3135 DONALD DOUGLAS LOOP S, SANTA MONICA, CALIF. 90405-6186
PHONE #: 1-800-421-9995
FAA ARS ZY2R362L

WARRANTY

AIRCRAFT OWNER PLEASE NOTE

Santa Monica Propeller Inc. thanks you for purchasing this propeller or overhaul from our facility.

Santa Monica Propeller Inc. is proud to offer what we believe to be the most comprehensive **Warranty** in the aviation industry.

Santa Monica Propeller Inc. warrants this propeller to be free of defects in material and craftsmanship for *TWO (2) YEARS* or *ONE THOUSAND (1,000) HOURS* from time of overhaul, whichever comes first.

This **WARRANTY** is not pro-rated and includes commercial usage.

This **WARRANTY** entitles purchaser to repairs by **Santa Monica Propeller Inc.** only.

Assemblies must be shipped prepaid and will be returned within five (5) working days F.O.B. **Santa Monica Propeller Inc.**

Assemblies must be accompanied by the original work order (invoice) **NO EXCEPTIONS.**

This **WARRANTY** is transferable per conditions on reverse.



3135 Donald Douglas Loop S
Santa Monica, CA 90405-6186

FAA ARS ZY2R362L
(310) 390-6233
TOLL FREE
(800) 421-9995

[Handwritten Signature]

Authorized Signature

K29133

Work Order #

2/9/15

Date



PROPELLER MAINTENANCE RECORD

Position ONE

Propeller Model 74DM7-0-64

Propeller S/N A 52378

Blade Design ~~Ø~~

Blade S/N's

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather X

Start Lock X

Low 64"

Reverse X

Aircraft Manufacturer AMERICAN AVI

Aircraft Model AA-1A

S/N 0029

Registration N9329L

STC No. _____

Governor _____

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

T.T.S.N. VNKN


DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
Feb. 10, 2015	W/O	K 29133	
		<p>PROPELLER COMPLETELY OVERHAULED. ANGLES AND ALIGNMENT CHECKED. PROPELLER PENETRANT INSPECTED, REFINISHED, ALODINED AND PAINTED. PROPELLER BALANCED.</p>	
		<p>THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER THIS INVOICE NUMBER AND DATE.</p>	
		<p>SIGNED <u>[Signature]</u> AUTHORIZED SIGNATURE F.A.A. A.R.S. No. ZY2R362L</p>	
2-12-15	0403.28 0.0 SMWH	<p>W. STALLED THIS PROPELLER ON THIS AIRCRAFT (GRUMMAN AA1A SN 0029) N9329L.</p>	<p><u>[Signature]</u> ANDRES GONZALEZ A&P 3290258 IA</p>

BILL'S AIR CENTER INC.
W.O. # 0341

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
3-10-16	0416.78	SMOH: 13.5	
BILL'S AIR CENTER INC. W.O.#		INSPECTED THIS PROPELLER DURING ANNUAL INSPECTION & WAS FOUND IN AIRWORTHY CONDITION.	
			 ANDRES GONZALEZ A&P 3290258
4-28-17	0425.99	SMOH: 22.7	
		INSPECTED THIS PROPELLER DURING ANNUAL INSPECTION AND WAS FOUND IN AIRWORTHY CONDITION	
		 Denys M. Leigh-Taylor A&P 3486563 A	

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
11-1-18	457.27	SUMH: 53.98	
BILL'S AIR CENTER INC. W.O. # 1881		SERVICED + INSPECTED THIS PROPELLER ANNUAL INSPECTION.	
			ANDRES GONZALEZ A&P 3290258 IA

Prop Model:
74DM7-0-64
Prop S/N:
A52378
Reg. Num:
N9329L
Work order:
20-31210



3135 Donald Douglas Loop S
Santa Monica, CA 90405 USA
Phone: 310-390-6233
FAA Repair Station ZY2R362L


Date: 07/01/2020

FIXED PITCH PROPELLER WAS REPAIRED. CHECKED ANGLES, ALIGNMENT TRACK MEASURED, REFINISHED, ALODINED, PAINTED AND STATICALLY BALANCED I.A.W. SENSENICH SERVICE MANUAL #SPRM 590. CONTINUE TIME. TIME UNKNOWN

The Aircraft and/or component identified above Was repaired and inspected in accordance with Current Federal Air Regulations and was found Airworthy for return to service. Pertinent details Of the repair are on file at this agency under this Invoice number and date.

SIGNED 
Authorized Signature F.A.A. A.R.S. No. ZY2R362L

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
7-1-20	533.78	REMOVED PROPELLER FOR O/H & REINSTALLED.	
BILL'S AIR CENTER INC. W.O. # 2732			ANDRES GONZALEZ A&P 3290258 IA

7
58 IA

4233 Santa Anita Ave.
Ste. 3 Hangar 8
El Monte, Ca. 91731
(626) 274-2137
DATE: 7-1-2025

PROP



MAKE: GRUMMAN MODEL: AA1A S/N: 0029 REG: N9329L TACH: 0559.44 A.F.T.T.: 3390.60

MAKE: SENSENICH MODEL: 74 DM7-0-64 S/N: A52378 S.M.O.H.: 559.44 PROP TOTAL TIME: UNKNOWN

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED I.A.W AN ANNUAL INSPECTION I.A.W FAR 43 APPENDIX D AND HAS BEEN DETERMINE TO BE IN AIRWORTHY CONDITION.

DETAILS ON FILE UNDER W/O# 4657


ANDRES GONZALEZ A&P 3290258 IA

