| YEAR: | RECORDING TACH TIME | TODAYS FLIGHT | TOTAL TIME IN SERVICE | **Description of Inspections, Tests, Repairs and Alterations** Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (*See* back pages for other specific entries.) |
|---|---|---|---|---|
| | | | | N282CD |
| | | | | 4/8/2026 Cirrus SR22 S/N 1136 Aircraft hobbs meter 1229.7 Complied with Annual inspection this date as per FAR 43 appendix D and using Cirrus SR22 Inspection guide as a reference. Inspected ELT Model ME 406 P/N 453-6603 as per Artex installation and maintenance manual 570-1600 rev E. Ops checked as per FAR 91.207(d). Removed and installed new engine induction filter P/N BA-24. All AD's checked through Bi-weekly 2026-07. Found AD 2024-24-11 (Power Lever Crack) N/A by P/N installed as per Cirrus SB2X-76-05. I certify that this Aircraft has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. Airwerks LLC. Marvin Coolidge Marvin Coolidge AP2757107IA. |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |